


Pore Pressure Dissipation Test Results




Test CPT-1
Test Depth - ft 15.03
Test Duration - s 900

PROJECT: EQUIS Geotech Demo
SITE: 123 Discovery Road
Seattle, WA

earthsoft
125 S. Alcaniz St. Pensacola FL

PROJECT NUMBER: EQUISGEOTECH
CLIENT: EarthSoft
Bellevue, Wa

Pore Pressure Dissipation Test Results



Test	CPT-1
Test Depth - ft	29.99
Test Duration - s	900

PROJECT: EQUIS Geotech Demo
SITE: 123 Discovery Road Seattle, WA



125 S. Alcaniz St. Pensacola FL

PROJECT NUMBER: EQUISGEOTECH
CLIENT: EarthSoft Bellevue, Wa